

TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

Reason For Inspection:

1st Weekly

2nd Weekly

DATE: 8.15 ·//

State Route (SR) / US Ro	ute or Road Name and [Description:		Are corrective actions required by this inspection report (Y/N):			
	Wolf River Blvd	v.			No		
County(ies):	TDOT PIN:	NPDES Permit (NOC)	#:	Number of New	Number of Recurring	Number of New	Number of Un-Corrected
Shelby	101615	TNR153299	TNR153299		Corrective Actions:	Sediment Releases:	Sediment Releases:
TDOT Construction No.: 7994-1535-54	TDOT Contract No.:	Contractor: Acuff Enterprises Inc.		0	0	i.	
I certify, under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated information presented. Based on my inquiry of the person or persons who				C Inspector and Title (p	an and the state of the state o	Signature:	Starp
manage the system, or those persons directly responsible for gathering the information, I cerify that inspections of storm water discharge points (outfalls) and of erosion and sediment controls have been performed as recorded in the table above. I certify that erosion and sediment controls in the drainage area of the identified outfall where installed as planned and designed in working order as				r EPSC Inspector and Title (print or type): Tom Acuff		Signature:	
recorded in the lable above. I am aware that there are significant penalties for submitting false information, including the possibility of fine and impresonment for knowing violations.				C Project Manager ype): Timothy Biel	rdz	Signature:	BY

TDOT EPSC Inspection Weekly Rainfall Data Log

		Predicted	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall		TDOT/Contractor Agrees with Inspection Report:
Date	Day of Week	Precipitation	Gauge 1	Gauge 2	Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	NO or (YES)
		(%)	(in)	(in)	(in)	(in)	(in)	(in)	(hr)	If No, explain and initial:
8/14/11	Sunday	0			N/A	N/A	N/A	N/A		
8/15/11	Monday	10	0.20	0.50	N/A	N/A	N/A	N/A	1	
3/16/11	Tuesday	10			N/A	N/A	N/A	N/A		
	Wednesday	20			N/A	N/A	N/A	N/A		
8 /17 /11 8 /1/ /1/	Thursday	30			N/A	N/A	N/A	N/A		
8/12/11	Friday	40		100 C	N/A	N/A	N/A	N/A		
8 / j2 // 8 13 11	Saturday	60			N/A	N/A	N/A	N/A		
J	Sunday				N/A	N/A	N/A	N/A		
	Monday				N/A	N/A	N/A	N/A		
							***************************************		•	(Additional pages may be attached, if needed)

Predicted Precipitation Source:

www.weather.com

Page 1 of 7

	State/US Route
RE	

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date	8/15/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	6/3/2011	T = 6-3-11	22,35	S	STABLE (NO ACTION NEEDED)
1A	1	21+50	RT	7/5/2011	T = 7-5-11	33,35	S	Currently stable, Monitoring BMP's
1B	1	22+00	RT	8/15/2011	T= 3-25-11	24,33,35	FM	Currently Active, Monitoring BMP's
1C	1	21+00	LT	8/11/2011	T = 7-27-11	12,35,41	FM	Currently Active, Monitoring BMP's
2A	1	33+50	LT	8/11/2011		16,24	FM	Stabilize ramp leading into Lateral.
2B	1	35+50	LT	8/11/2011	T= 7-18-11	16,24	S	Currently stable, Monitoring BMP's
3	1	34+50	LT					The area has not been disturbed.
4	1	40+00 N.E. side, top of Ditch Bank	RT	8/8/2011		16,33,43	FM	Currently Active, Realignment of Ditch Channel,Monitoring.
5A	1	49+00	RT					The area has not been disturbed.
5B	1	50+00	RT					The area has not been disturbed.

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15	Temporary seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	I	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#3):	
				43	Stream Realignment		

CONDITION CODES

زو	OFTHE	577
(S)	AGRICUJI	URE
	OHME!	
	1796	* 3/

State/US Route or Road Name:

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT	8/11/2011		16,24	FM	Corrective actions are to be made.
6	1	56+00	LT					The area has not been disturbed.
7	1	60+00	RT		44-44			The area has not been disturbed.
8A	1	73+00	RT	8/15/2011		16,24,42	FM	Currently active construction zone. See Photo
8B	2	75+50	RT	8/8/2011	T = 7-5-11	16,24,35,41	S	Currently Stable, Monitoring BMP's.
8C	1	71+00	LT	8/15/2011		16, 42	FM	Currently active construction zone. Add filter socks. See Photo
8D	2	75+50	LT	8/8/2011	T = 7-5-11	16,35	S	Currently Stable, Monitoring BMP's.
8E	1	71+50	LT					The area has not been disturbed.
9A	2	80+00	RT	8/11/2011	T = 8-11-11	15,16,33,35	s	Currently Stable, Monitoring BMP's.
9B	2	80+00	LT	8/1/2011	T = 8-2-11	16,17,35	S	Currently Stable, Monitoring BMP's.

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy, Daily M Maintenance Temporary Diversion Berm or Ditch 2 16 30 Temporary Mulch Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) Temporary Slope Drain 3 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing С Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 **Enhanced Silt Fence** Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutler, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 39 Gabion S Turbidity Barrier / Silt Boom Stable (No Action Needed) 12 Machined Rip Rap 26 Other (O31): Temporary Stream Diversion 40 Sheet Pilling 13 Geotextile Other (O#2):____ 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Permanent Seeding with Mulch or Sod Other (O#3): 14 28 Mineral Aggregate Base on Subgrade **Bridge Construction**

CONDITION CODES

State/US Route or Road	State/US	Route or Roa	d Name:
------------------------	----------	--------------	---------

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	8/15/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	8/1/2011	T = 8-2-11	16,20	S	Currently stable. Monitoring BMP's.
10A	2	85+00	RT	8/15/2011	T = 8-11-11	15,16,24,35	FM	Stabilization will be required. See Photo
10B	2	85+00	RT	8/15/2011	T = 8-11-11	15,16,24,35	FM	Stabilization will be required. See Photo
10C	2	85+50	LT	8/8/2011	T = 8-8-11	16,35	FM	Stabilization is required. See photo
10D	2	84+50	LT	8/8/2011	T = 8-8-11	10,16,35	FM	Stabilization is required. See photo
11A	2	92+50	RT	8/11/2011	T = 8-11-11	15,16,24,35	FM	Remove temp. rock dam at end of each day after construction.
11B	2	92+50	LT	8/11/2011	T = 8-11-11	10,32,35	FM	Debris to be removed. See Photo
11C	2	92+00	LT	8/4/2011	T = 8-8-11	35	S	Currently stable.
	1	11+28	LT	8/11/2011	T = 6-3-11	19,35	FM	Currently stable, Monitoring BMP's
	1	13+40	RT	8/11/2011		23,29,30	FM	Daily cleaning will be required, until further notice.
	1	107+75	CL CL	8/11/2011	MEASURE CODES	23,29,30	FM	Daily cleaning will be required, until further notice.

EROSION AND SEDIMENT CONTROL MEASURE CODES

CONDITION CODES Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy, Daily Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control Upgrade Needed (Failure Noted) Temporary Slope Drain 3 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions Sand Bags 8 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Other (O31): Sheet Pilling 13 Geolextile Preserve Natural Resource / Buffer Zone 27 Haul Road 41 Other (O#2): 14 Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

State/US Route or Ro

toll IS Doute or Dood Name:	Wolf River Blvc
ate/US Route or Road Name:	vvoii River Bivo

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	8/15/2011	

Outfall Name or Station No. *(Existing Structure)	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
* 109+51	2	East side of WRB	RT	8/15/2011		19,22	S	Stable, monitoring BMP's.
* 109+11	2	South side of Farmington	RT	8/15/2011		19,22	s	Stable, monitoring BMP's.
* 12+80	1	North side of WRB	LT	8/15/2011		19,22	S	Stable, monitoring BMP's
	1	Walking Trail 36+00	LT	7/20/2011		5,35	s	Currently stable, Monitoring BMP's
	1	Sta. 29+50 Slope	LT	7/20/2011		16	S	Currently stable.
	2	107+00 - 107+30	LT	7/28/2011		16,35	S	Currently stable.
	2	76+50 - 103+46	RT	8/11/2011	T= 8-11-11	15,16,35	FM	Hydroseed again per TDEC. See photo
	1	15+60	RT	8/4/2011	1,30,000	35	s	Monitoring BMP's
	1	6+75	LT	8/11/2011		19,22	FM	Stable, monitoring BMP's.
	1	25+00 EROSIO	RT ON AND SEDIMEN	8/15/2011 T CONTROL ME	ASURE CODES	41	FM	Additional measures required. See Photo CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily Maintenance Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner Replacement Needed Rock Check Dams Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing С Cleaning Needed Sediment Removal 20 Riprap Outlet Structure Enhanced Silt Fence Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube Too Wet to Work Conditions Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Other (O31): Sheet Pilling Other (O#2): Geotextile 13 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Permanent Seeding with Mulch or Sod 14 28 Other (O#3): Mineral Aggregate Base on Subgrade **Bridge Construction**



Outfall 8A Sta. 73+00 LT Currently active construction zone. (FM)



Outfall 8C Sta. 71+00 LT Currently active construction zone. (FM)




Outfall 10A Sta. 85+00 RT & Outfall 10B Sta. 85+00 RT Currently active, stabilization will be required. (FM)



Outfall 10C Sta. 85+50 LT & Outfall 10D Sta. 84+50 LT Additional socks will be required. (FM)



City of Germantown 1920 S. Germantown Road Germantown, TN 38138



Outfall 11B Sta. 92+50 LT Debris to be removed. (FM)



Sta. 76+50 – 103+46 RT Temp. seeding with mulch needs to be reapplied per TDEC. (FM)



Sta. 25+00 RT Additional measures (filter socks) are required. (FM)

No Picture



City of Germantown 1920 S. Germantown Road Germantown, TN 38138